



Measuring low light levels

...requires extremely low dark currents coupled with maximum useful sensitivity. The EMI 6256, a 13-stage venetian blind 2" photomultiplier tube has the essential characteristics that are necessary for low light level applications. The unique 10mm cathode-DI geometry, together with the ultra-stable EMI venetian blind design, has resulted in its widely successful use in astronomy, biology and spectrophotometry. The EMI 6256B has a quartz window and the S-11 cathode (S-13) which has a peak quantum efficiency of 17% at 4,200 Å. The EMI type 6256S has 5 to 10 times lower dark current than the 6256B, and should be used when system performance is dark current limited. This type is also available for visible light applications as 9502B/9502S, or with 11 dynodes as 6094B/6094S. Many other EMI photomultiplier tubes are available for special applications from stock in sizes from 1" to 12". EMI photomultiplier tubes are available through qualified engineering representatives located in major marketing areas throughout the United States. A request on your company letterhead will bring you the name of your nearest representative as well as a copy of our latest catalog.



Whittaker
CORPORATION
GENCOM DIVISION

80 Express St., Plainview, L.I., N.Y.
516-433-5900 TWX 516-433-8790
*EMI ELECTRONICS, LTD.

SEARCH AND DISCOVERY

energies as low as 10^{-10} eV, much smaller than was thought possible.

In a talk at the December APS meeting, Witteborn described a new, enlarged apparatus with a free-fall region 5 cm in diameter and 300 cm long. Preliminary results indicate that freely falling electrons experience the same gravitational force as electrons bound in a metal (in agreement with a recent theoretical paper by Leonard Schiff and M. V. Barnhill of Stanford). By passing a current through the walls of the drift tube a known uniform force smaller than gravity could be applied on the otherwise freely falling electrons. Comparison of the time-of-flight distributions taken with various applied forces demonstrated that the slowly moving particles were electrons and that no other net forces larger than $\pm 0.2 mg$ existed within the drift tube (where m is the electron's inertial mass and g is 980 cm/sec^2).

To solve the more difficult problem of obtaining low-energy positrons, a source is being developed by John Madey, a graduate student. Positrons emitted from a radioactive source will be slowed down by multiple collisions with gas atoms. Witteborn notes that their experiment will be the first direct determination of the gravitational properties of antimatter.

Bevatron Shut Down 3 Months: Metal Fatigue in Alternator

Metal fatigue has cracked the dovetail on the rotor of a Bevatron alternator. Repairs will shut down the Berkeley 6-GeV proton synchrotron for at least three months. During routine maintenance in December, Bevatron technician W. B. Thompson found some indications that one of the poles had cracked; further inspection showed that the other Bevatron alternator also had cracked poles. Westinghouse is fabricating new parts for the alternator, which is expected to be running again around March.

The alternators, each rated at 46 MW, energize the large Bevatron magnet; they are pulsed about 10 times per minute. Similar alternators are used at Brookhaven, CERN, Argonne

and NIMROD in the United Kingdom.

Last year metal fatigue on a NIMROD alternator caused a crack while the accelerator was running; the moving rotor grabbed the stationary stator and tore it to pieces. The damage took almost a year to repair. When *PHYSICS TODAY* spoke to Harold Vogel (who is in charge of the Bevatron power supply), he noted that the NIMROD fatigue failure occurred after only about 7 million alternator pulses, whereas the Berkeley machine, running since 1954, has been pulsed about 37 million times. The Brookhaven AGS, running since 1959, has already been pulsed 57 million times, because it pulses more frequently.

Brookhaven accelerator people, concerned over the possibility of metal fatigue in their own alternators, are studying the Bevatron failure. They have inspected the AGS alternator in detail and found no signs of fatigue cracks there.

Radiation-Damaged Hose Causes Fire at AGS

A fire at the Brookhaven AGS on 9 Dec., which destroyed the coils on one magnet and downed the accelerator for six days, is a symptom of the radiation damage that is becoming a serious problem at the facility. Because the accelerator is operated at 15 times its original design intensity, water hoses burst, magnet insulation turns a sickly greenish yellow and some of the AGS staff is being exposed to almost the allowable radiation limit. So we were told by Kenneth Green, chairman of Brookhaven's accelerator department. Green feels that the AGS in its present configuration cannot continue running at its average intensity, 1.5×10^{12} protons/pulse, for more than another year or so. However, he expects that the AGS conversion project (*PHYSICS TODAY*, September 1964, page 98) will soon relieve some of the radiation problems involving men and equipment.

Burst water hoses have occurred with increasing frequency at the AGS since the neoprene rubber hoses used to cool magnet coils last only two or three months in the intense radiation. To protect equipment from water damage, operating personnel had spread polyethylene sheets. On 9 Dec. a